

Service Technical Information

MODEL NO. XH-A1000
SUBJECT Notes on replacing μ -COM

REF.No. :G - A0 - 080 - E0

DATE :25. SEP. 2000

<CONTENTS>

The CD mechanisms mounted on the models above are broadly divided into two different types.
 μ -COM used on the CD mechanisms are not compatible with each other on different types.

When replacing μ -COM, be sure to identify a CD mechanism with reference to the table below:

Determine a type of CD mechanism by a Pick up that is mounted.

1. AZG-1 ZD3 / ZD4 KSS-213F is mounted
2. AZG-1 ZD8 KSM-880 is mounted

Servo (IC)	KSS-213F 	KSM-880 
Digital Servo (LA9235M, LC78641E)	8A-MTM-602-110 LC876580W-5N99	8A-MTM-601-010 LC876580W-5K53

Ref.	Parts Code	Description	Remarks
IC101	8A-MTM-601-010	C-IC,LC876580W-5K53	AZG-1 ZD8
IC101	8A-MTM-602-110	C-IC,LC876580W-5N99	AZG-1 ZD3 / ZD4

G	R	Code No.	Access Code	Modified Ser. No.	Parts Schedule
-	-	-	-	-	NOV.2000