

MAINTENANCE

In general, the Model 810 Transistor Radio Tester should give long uninterrupted service. Normally, any tube can be replaced with a good standard equivalent tube without the necessity of re-adjustment or re-alignment of the Tester. Figure 3 shows the location of these tubes. It is suggested that if the tester should need maintenance other than routine replacements, the factory service department or one of our authorized service stations be contacted for service or advice.

A wiring diagram is shown in Figure 4 to aid in maintenance work.

Code No. 2490-342